

TO: Frank Donovan, New England Telephone

5 August 1969

From: J. H. Saltzer, M.I.T. Project MAC

Subj: Known telephone problems related to 103E dataset/level8 installation.

Datasets believed to be down:

- ~~A5 Problem unknown~~
- ~~A15 Will not handshake properly~~
- ~~A19 Problem unknown (After answer, ring indicator flashes intermittently.)~~
- A22 Problem unknown
- B1 Ringer buzzes when in use
- B4 Intermittent: sometimes returns a low pitched hum rather than ringing. Also sometimes hangs up immediately following handshake.

Datasets with small bugs but working well enough to use:

- A23 Flashes (as though ringing) when in use.
- ~~A33 Carrier detect light does not work. (May be fixed.)~~

Troubles presumed to be in the Dataswitch:

Auxiliary Trunks <sup>66</sup>68 and 101: The 103E busy-out function does not prevent callers from attaching to and ringing on these trunks.

Datasets which hang up very slowly if not properly hand-shaken before hangup: (May be trouble in 103E or in Dataswitch?)

- A20 (Aux Trunk 106)
- B4 (Aux Trunk 130)
- B5 (Aux Trunk 131)

5 August 1969

Additional notes:

1. As of 5 August, we have not begun to make any significant use of the level 7 Datasets; more problems will probably show up when we do.
2. ~~A large number of complaints about dialing 8 and receiving a trunk which does not answer, and which cannot be resolved as Multics bugs or unbusyable data sets, lead us to suspect that there are wiring errors in the dataswitch level 8 grading. We will continue to trace these complaints to see if we can get a firmer hold on this problem. Unfortunately, many of them arise during evenings and weekends, during which time assistance in tracing cannot be obtained from the dataswitch room.~~