

RECEIVED
JUN 17 1976
U. H. SALTZER

FORUM LIST

D. Clark

C. Clingen

W. J. Flaherty

J. Gintell

P. B. Kelley

C. Kessler

G. Lundberg

J. Regester

✓ Prof. J. Saltzer

Honeywell

TO: List of Attendees cc: List

SUBJECT: Forum Minutes for June 2, 1976

ATTENDEES: G. Ackerman-Lewis W. McFall
W. J. Burner R. A. Roach
R. J. Chevalier L. J. Ryan
E. D. Kleinow J. R. Steinberg

HARDWARE - E. D. Kleinow

Processors

- . CPUB - CD board (cache) failed and was replaced.
AB board failed and had chip replaced.
- . CPUA - 11 crashes related to this CP!
The SCAN WITH MASK change, installed earlier, was removed by FED because it appeared to be causing the CMP errors. This change is still in CPU-B.

MPC 190

- . Intermittent DI board failure.
FED replaced. B units down 1 day.
- . Drive 8 (A) belt failed.
FED replaced.
- . Drive 1 (A) interlock switch failed.
FED adjusted.
- . Drive 1 (B) GDC board failed and replaced by FED.
- . Drive 5 (B) DRI board replaced.
- . DN 355 - LSLA failing chip replaced.
- . PRT 301 Unit down (since last nite) with VFU alerts.
Part on order.

Leo Ryan reviewed system statistics over the last month and noted the major share of crashes were disk related. FED agreed and pointed out that the bulk of all disk failures were caused by the 190B units. These units will be removed from MIT by mid July.

SOFTWARE - G. Ackerman-Lewis

System 28.5b running.

System 28.6 being worked on. This will include a real time scheduler.

BILLERICA

Roger Roach noted that Billerica usage had gone up in the last two weeks and that IPC needs two full weeks notice before pull-out of 190-B's can be completed.

A handwritten signature in black ink, appearing to be 'GAL' or similar, located in the lower-left quadrant of the page.