

- Daley: Hardware configuration is screwed up,
1. not same as DTC
 2. not same as DC.64
 3. CPA + B differ
 4. Interrupt cells forced to look like control A.

Both look cards ?