

TO: Distribution  
FROM: George T. Williams  
DATE: June 13, 1977  
SUBJECT: Installation of MSS 31.4b

## I. SYSTEM CHANGE LOG

## MCR MODIFICATIONS FOR 31.4b

2591 Fixes a bug in dn355 delay queue mechanism which sometimes caused terminal output to be stuck in ring 0 under heavy load.

## II. SEGMENT CHANGE LOG

SEGMENT NAME	BOUND SEGMENT
dn355.pl1	R bound_355_wired
hardcore.header	R -

---

Multics Project internal documentation. Not to be reproduced or distributed outside the Multics Project.