

TO: Distribution
 FROM: David M. Jordan
 DATE: March 13, 1974
 SUBJECT: Installation of BOS 1.34

The BOS system 1.34 was updated at 3:30 PM on Tuesday, March 12, 1974. This system included changes to the methods of reporting printer and tape errors and a fix for an initialization bug in the DataNet 355 code.

I. System Change Log

Chng MCR Change

0012 177 Added code to report printer errors on the console and
 372 to report tape errors only when the tape is unloaded.
 0013 351 Fixed a bug in the initialization code for the 355.

II. Segment Change Log

<u>Segment Name</u>	<u>Change #</u>	<u>Segment Name</u>	<u>Change #</u>
d355.build355 *	R 0013	ptpkg.alm	R 0012
gint.map355	R 0013	restor.alm *	R 0012
ntape.alm	R 0012	save.alm *	R 0012

Include Files

getcon.incl.alm	R 0012	sav_loop.incl.alm	R 0012
getprt.incl.alm	R 0012		

* No source change, just recompiled (or rebuilt) for new include (or 355 object) segments.

III. Header Change Log

There were no changes to the BOS header.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.