

TO: Distribution  
 FROM: David M. Jordan  
 DATE: March 26, 1974  
 SUBJECT: Installation of BOS 1.35

The BOS system 1.35 was updated at 2:30 PM on Monday, March 25, 1974. This system included the final changes for the g115 remote printer and fixes for bugs in the DataNet 355 write de-queuing subroutine and the handling of HSLA configuration cards.

### I. System Change Log

<u>Chng</u>	<u>MCR</u>	<u>Change</u>
0014	172	Final BOS changes for the g115 remote printer interface.
0015	407	Fixed a bug in the write de-queuing subroutine of the DataNet 355 software.
0016	416	Fixed a bug in the handling of configuration cards which resulted in all but the first HSLA cards to be ignored.

### II. Segment Change Log

<u>Segment Name</u>	<u>Change #</u>	<u>Segment Name</u>	<u>Change #</u>
blast.alm	R 0016	g1cm.map355	R 0014,
d355.build355 *	R 0014,		0015
	0015	1d355.alm	R 0014,
ghsa.map355	R 0014		0016

\* No source change, just rebuilt with new components.

### III. Header Change Log

There were no changes to the BOS header.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.