

To: Distribution
From: David M. Jordan
Date: April 19, 1974
Subject: Installation of BOS 1.36

The BOS system 1.36 was updated at 2:45 PM on Wednesday, April 17, 1974. Change # 0017 (MCR 438), which replaced the component ghsa.map355 in d355.build355, fixed a timing problem in the HSLA portion of the DataNet 355 software.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.