

To: Distribution
From: David M. Jordan
Date: July 31, 1974
Subject: Installation of BOS 1.38

The BOS system 1.38 was updated at 2:30 PM on Monday, July 31, 1974. Change # 020 (MCR 573), which replaced the d355 components ghsa.map355 and gicm.map355, fixed two bugs affecting the MDS 2400. Change # 021 (MCR 527), which replaced the d355 component gint.map355, fixed a bug in the handling of dual synchronous subchannels.