

To: Distribution
From: David M. Jordan
Date: September 16, 1974
Subject: Installation of BOS 1.40

The BOS system 1.40 was updated at 4:15 PM on Tuesday, September 10, 1974. The system included the addition of substitutable arguments for BOS runcom's, the ability to support URMPC peripherals, and various minor fixes and changes.

I. System Change Log

<u>Chng</u>	<u>MCR</u>	<u>Change</u>
0024	645	Added the capability for substitutable arguments in BOS runcom's.
0024	659	Fixed a bug in the management of the DUMP partition.
0024	702	Added the ability to run URMPC-type peripherals.
0024	703	Fixed a problem which sometimes resulted in lockup faults at a time when no handler was available.
0024	704	Fixed a numeric conversion bug in the scan routine.
0024	717	Modified the BOS bootload procedures to allow the use of a card reader on any channel instead of restricting the card reader to channel 16.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.

II. Segment Change Log

<u>Segment Name</u>	<u>Change #</u>	<u>Segment Name</u>	<u>Change #</u>
bosldr	R 0024	patch.alm	R 0024
fd355.alm *	R 0024	print.alm	R 0024
fdump.alm	R 0024	ptpkg.alm	R 0024
lf.alm *	R 0024	runcom.alm	R 0024
ld355.alm	R 0024	salv.alm	R 0024
loadm.alm	R 0024	setup.alm	R 0024
ntape.alm	R 0024	util.alm	R 0024

Include Files

bos_common.incl.alm	R 0024	getprt.incl.alm	R 0024
bos_iom_manager.incl.alm	R 0024	ldcom.incl.alm	R 0024
bos_toequ.incl.alm	R 0024	nextline.incl.alm	R 0024
bos_tv.incl.alm	R 0024	punch.incl.alm	R 0024
conv.incl.alm	R 0024	readc.incl.alm	R 0024
cvadd.incl.alm	R 0024	rwdisk.incl.alm	R 0024
error.incl.alm	R 0024	scan.incl.alm	R 0024
fdmp.incl.alm	R 0024	search.incl.alm	A 0024

* No source change, segment reassembled for new include files.

III. Header Change Log

There were no changes to the BOS header.