

TO: Distribution  
FROM: David M. Jordan  
DATE: August 18, 1975  
SUBJECT: Installation of BOS 1.45 & 1.45a

The BOS systems 1.45 and 1.45a were updated on Friday, July 25, 1975 at 11:30. BOS 1.45 includes the BOS changes necessary for the installation of the Multics Communications System (MCS) software in the 355. BOS 1.45a contained fixes for a problem in discriminating between terminal types and a problem with dialup of the ARDS terminals.

#### I. System Change Log

Chng MCR	Change
0035 431, 1081, 1082, 1110	Install the Multics Communications System (MCS) software in the 355.
0036 ---	Fix problem in discriminating between terminal types and a problem in dialing up the ARDS terminals.

---

Multics Project Internal documentation. Not to be reproduced or distributed outside the Multics Project.

## II. Segment Change Log

<u>Segment Name</u>	<u>Change #</u>	<u>Segment Name</u>	<u>Change #</u>
blast.alm	R 0035	gman.map355	D 0035
console_man.map355	A 0035	gmpm.condk	D 0035
control_tables.map355	A 0035	gptr.map355	D 0035
dn355_build355	D 0035	gssp.map355	D 0035
dia_man.map355	A 0035	hsia_man.map355	A 0035
dmp355.alm	R 0035	init.map355	A 0035
gcon.comdk	D 0035	interpreter.map355	A 0035
gdbg.map355	D 0035	ld355.alm	R 0035
ghsa.map355	D 0035	lsla_map355	A 0035
gicm.map355	D 0035	mcs.build355	A 0035
gint.map355	D 0035	scheduler.map355	A 0035
glsa.map355	D 0035	trace.map355	A 0035
control_tables.map355	R 0036	interpreter.map355	R 0036

## III. Header Change Log

The BOS header was changed to delete the entry for d355 and to add an entry for mcs.