

To: Distribution  
From: David M. Jordan  
Date: September 15, 1975  
Subject: Installation of BOS 1.46a

The BOS system 1.46a was updated at 4:05 PM on Tuesday, September 9, 1975. Change # 0040 (MCRs 1370 and 1383), which replaced `control_tables.map355`, `dia_man.map355`, and `hsla_man.map355` in the DataNet 355 core image mcs, fixed a design problem in the allocation of buffer space in the 355. This BOS system was installed in conjunction with MSS 26.4a which fixed the 6180 side of the problem.