

To: Distribution
From: David M. Jordan
Date: June 25, 1976
Subject: Installation of BOS 2.02

The BOS system 2.02 was updated at 3:25 PM on Monday, June 14, 1976. This system included: several changes to improve the reliability of SAVE and RESTOR, preparation for moving the data shared by BOS and Multics to the BOS toehold, the addition of the BOSTAP command, a change to allow the use of the new PRPH DSKn protocol, a fix for the reset-read problem in the FEP core image, and several other minor changes and fixes.

I. System Change Log

<u>Chng</u>	<u>MCR</u>	<u>Change</u>
0056	1638	Modified SAVE to report if a volume should be salvaged before saving.
	1651	Modified RESTOR to cause salvaging of a volume if read errors were encountered while restoring.
	1723	Fixed bugs which caused some device addresses to be interpreted incorrectly.
	1724	Fixed a bug in RESTOR which caused it to print incorrect data about tape contents and target disks.
	1725	Fixed several bugs in DUMP.
	1726	Fixed a bug in the processing of "IF SHUT".
	1727	Made preparations to allow the moving of data used by both BOS and Multics (the "flagbox" segment) into the BOS toehold. This will allow the data to remain consistent even if BOS is reentered.
	1733	Modified BOS to use "PRPH DSKn" configuration cards instead of "DISK DSKn" cards.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.

System Change Log (continued)

Chng MCRChange

1760 Added the BOSTAP command to allow the creation of new BOS tapes by BOS.

1893 Modified WRITE to output a blank line when invoked with no arguments.

0057 1792 Fixed a bug in the way the FEP handles reset-read.

II. Segment Change Log

<u>Segment Name</u>	<u>Change #</u>	<u>Segment Name</u>	<u>Change #</u>
apnd.alm	R 0056	hsla_mar.map355	R 0057
bostap.alm	A 0056	ncopy.alm	R 0056
control_tables.map355		ndisk.alm	R 0056
	R 0057	restor.alm	R 0056
dump.alm	R 0056	save.alm *	R 0056
fwload.alm	R 0056	setup.alm	R 0056
hsla_man.map355	R 0057	util.alm *	R 0056
lf.alm	R 0056	write.alm	R 0056
interpreter.map355	R 0057		

Include Files

argmul.incl.alm	R 0056	getportinfo.incl.alm	
bos_lom_manager.incl.alm			R 0056
	R 0056	inffit.incl.alm	R 0056
bosequ.incl.alm	R 0056	nextline.incl.alm	R 0056
config_cards.incl.alm		readc.incl.alm	R 0056
	R 0056	readf.incl.alm	R 0056
cvadd.incl.alm	R 0056	sav_util.incl.alm	R 0056
error.incl.alm	R 0056	writape.incl.alm	A 0056
fgbx.incl.alm	R 0056		
fs_dev_types.incl.alm			
	R 0056		

* No source change, recompiled with new include files.

III. Header Change Log

Change # 0056 modified the BOS header to add an entry for bostap.