

October 8, 1969

MEMORANDUM

To: Frank Donovan, New England Telephone  
From: Jerry Saltzer, M.I.T. Project MAC  
Subject: Known telephone problems related to 103E dataset  
installation.

Problems:

- A3 Panel indicator light is burned out.
- A6 Panel indicator lamp is burned out.
- A35 Disconnects after answering.
- B27 Hum on line instead of dial tone.
- B38 Panel indicator lamp is burned out.
- B39 Panel indicator lamp is burned out.
- B40 Panel indicator lamp is burned out.

The following datasets are susceptible to overload by the calling party,  
and thus do not work for some callers:

A2, A5, A6, A9, A15, A28, A31, A36, B2, B5, B8,  
B9, B14, B15, B17, B18, B19, B20, B22, B24,  
B26, B28, B29-32, B34-37.

JHS/bm

xc: Daley  
Corbato  
Grochow  
Operations