

F O R U M   L I S T

G. Ackerman-Lewis

D. Clark

C. Clingen

R. Daley

J. Gintell

G. Lundberg

J. Regester

Prof. J. Saltzer

R. Shoemaker

RECEIVED

NOV 5 1975

J. H. SALTZER

# Honeywell

TO: List of Attendees cc: List

SHBJECT: Forum Minutes for October 22, 1975

ATTENDEES: W. J. Burner E. D. Kleinow J. R. Steinberg  
R. J. Chevalier W. McFall  
W. J. Flaherty R. A. Roach  
P. B. Kelley L. J. Ryan

---

## HARDWARE - E. D. Kleinow

- Processors . DC confidence line had a one wire change installed per instructions from Phoenix.
- . SCU-B, Stor-A & Stor-B. Parity errors. FED retimed units. No parity errors since these adjustments were made.
- DSU190 . Spare 190B problem turned out to be caused by a faulty pack.
- . 190A, Area 11. Unit crashed, FED checked it out but found no problem. Unit is now running.
- PRT301 . Unit down 8 hours with intermitten problem. Diode block assembly was replaced.
- . Shear pin was replaced.
- . Problem reported last FORUM as a ribbon problem was found to be a ribbon guide problem. FED replaced shield on gate assembly.
- PRT202 . Unit up and in use. FED has compiled an extensive list of spare parts to be ordered.
- MTH505 . Write error problem. Leo is running test on 3M tapes to determine if high error rate is a media problem.

SOFTWARE - P. B. Kelley

- . System MSS.27.1 installed and running.
- . ARDS terminal ran away (overloaded buffer) causing system crash.

BILLERICA - W. J. Flaherty

- . Dump map requested to be sent to R. Reeves.
- . Request install of package to report use of portable terminals.
- . 40% of projected Billerica workload is now using MIT system.
- . 3 DSU190-B to be shipped from Billerica to MIT this week.

A handwritten signature in black ink, appearing to be 'WJF', located in the lower-left quadrant of the page.