

Published: 02/20/68

Identification

Correction to BD.7.01  
R. M. Graham

In figure 7 the nop instruction should contain a du modifier. This prevents the GE 645 from generating an unnecessary page fault in certain situations.