<u>F O R U M   L I S T</u>

W. J. Burner

D. Clark

C. Clingen

J. Gintell

C. Kessler

G. Lundberg

J. Regester

L. Ryan

Prof. J. Saltzer

Honeywell

TO: List of Attendees

SUBJECT: Forum Minutes for August 25, 1976

ATTENDEES: G. Ackerman-Lewis   W. McFall
             R. J. Chevalier   R. A. Roach
             P. B. Kelley   J. R. Steinberg
             E. D. Kleinow

HARDWARE - E. D. Kleinow

Memory C

- Parity errors caused several crashes. FED replaced
  failing bit mother board.

Processors

- Processor A slow down caused by FCO installed for
  Strobe-Nul. FED found errors with this (wire broken)
  and replaced it with board swap from CISL. FCO
  reinstalled on Tuesday.

190A

- Firmware crashed during unattended service. FED reloaded
  system and ran with no further MPC problems. Will monitor.

SOFTWARE - G. Ackerman-Lewis

- System 28.11c running.

- System 29.0 waiting for FCO's to be installed. May be
  ready next week.

- IMP DIM bug crashed system twice. Bug has temporary fix.