TO: Distribution

FROM: David M. Jordan

DATE: September 19, 1973

SUBJECT: Installation of MSS 20.11h

    The hardcore system, MSS 20.11h, was installed at 8:30 PM on Monday, September 17, 1973. This system included a fix for a reused address bug and part of a change to allow process destruction without waiting in ring 0. The system libraries were updated at 2:55 PM on Tuesday, September 18, 1973.

I. System Change Log

Change #	Change
1138	Fixed a reused address bug in pc_abs.
1139	Modified deact_proc to allow process deactivation without waiting in ring 0.

II. Segment Change Log

Segment Name	Bound Segment	Change #
deact_proc.pl1	bound_process_creation	R 1139
hphcs_.mexp		R 1139
pc_abs.pl1		R 1138
pxss.alm		R 1139

Bind Files

bound_process_creation.bind		R 1139

III. Bound Segment Change Log

Bound Segment	Change
bound_process_creation	Replaced deact_proc

IV. Header Change Log

There were no changes to the hardcore header.