To: Distribution

From: David M. Jordan

Date: September 15, 1975

Subject: Installation of MSS 26.4a

The hardcore system, MSS 26.4a, was installed at 3:oo PM on Friday, September 5, 1975. Change # 1491 (MCRs 1370 and 1383), which replaced dn355.pl1 in bound_355_wired and tty.incl.pl1, fixed a design problem in the allocation of buffer space in the DataNet 355 which had resulted in numerous crashes. The system libraries were updated at 3:40 PM on Tuesday, September 9, 1975.