Honeywell

J. H. Saltzer
for your info

To: List of Attendees

Subject: FORUM Minutes for 7 May 1974

cc: WJ Burner
     CT Clingen
     RC Daley
     JW Gintell
     RE Hoffman
     JR Steinberg

Attendees: RJ Chevalier   DA Kayden   LJ Ryan
            RM Gross   ED Kleinow
            DM Jordan   RA Roach

HARDWARE   ED Kleinow

--DSU190's - Area 6 problems currently off-line with Search Alerts.
             FED working on it.

--DSU180's - One unit down, bad board in power supply. FED replaced
             it and it ran okay.

--PRT301   - Micro Switch failed on paper stacker. FED replaced it
             and it ran okay.

--DN355   - Parity in HSLA Subchannel. FED investigating this one.

--MTH500   - Quality Assurance Engineer from Peripheral Operations
             Oklahoma City at MIT to discuss condition of MTH500.
             Looks like drive No. 3 has been most inconsistant to
             date. (2) 7 channel drives have been removed and will
             be replaced with (2) 500's as soon as Leo Ryan completes
             arrangements.

SOFTWARE   DM Jordan

Six software crashes occurred last week.

Bug #260 was corrected with the installation of the new TTYDIM.

RJC/kmp