Honeywell

To: List of Attendees   cc: WJ Burner
                                                           CT Clingen
Subject: FORUM Minutes for 5 March 1974   RC Daley
                                                           JW Gintell
Attendees: RJ Chevalier   DA Kayden   RE Hoffman
           RM Gross   ED Kleinow   LJ Ryan
           DM Jordan   RA Roach   JR Steinberg

HARDWARE

New Bulk Store - CSM4 receiving correctable errors. FED located bad
          DLX board. Replaced it and it ran error free.

Outstanding FCO's - 9 hours on processors; 28 hours on hold.

DSU191 - Area 4, 3 and 11 had problems during week causing three
          crashes. FED monitoring this problem closely.

DN355(service) - LSLA12 - faulty chip on BA board caused downtime.
          FED located and replaced it. Results okay.

FRED (IMP Interface) - Bits were being dropped in read channel
          Peripheral switch was bad; FED replace and it ran okay.

Hardware Bug List

   #67 - Fix installed in Processor B this morning. Not checked out.

   #65 - Fix installed. Needs to be checked out by FED/PCO.

SOFTWARE. DA Jordan

Priority #1 Bugs

   #243 - Ring 0 NCP is version 1 pl-1. Wells says he has fix but
          its not submitted for installation yet.

   #198 - Possibly lost notify -- Webber assigned and feels he has
          located the possible cause of the error condition. Fix
          not submitted yet.

Other

   Roach asked that CISL be requested to place emphasis on the
   development of a package to resolve the handling of bad disk space.

RJC/kmp