

RECEIVED

APR 1 1975

U.S. DEPARTMENT OF JUSTICE

F O R U M L I S T

D. Clark

W. Burner

C. Clingen

R. Daley

J. Gintell

D. Jordan

G. Lundberg

J. Regester

Prof. J. Saltzer

R. Shoemaker

Honeywell

TO: List of Attendees cc: List

SUBJECT: FORUM Minutes for August 13, 1975

ATTENDEES: G. Ackerman-Lewis W. McFall
R. J. Chevalier R. A. Roach
P. B. Kelley L. J. Ryan
E. D. Kleinow J. R. Steinberg

Hardware- E. D. Kleinow

*Memory-

- . SCU-C STOR-B had faulty cable. FED replaced.
- . SCU-B STOR-A lost power. Voltage regulator board replaced.
- . SCU-A STOR-A FED spared out bit 32.

*Bulk Store-

- . Board failed causing system crash. FED replaced board.

*Tapes-

- . Two of the MTH505's have increasing error rates. FED will replace heads.

*PRT301-

- . Unit down with faulty motor. Replacement motor was the wrong one. FED rebuilt original unit as a temporary fix.
- . Hood problems again today. Shear pin broken.

Software-G. Ackerman-Lewis

- . MSS26.2 Installed
- . BUG No. 315 is not fixed, contrary to Availability Report.
- . I/O DAEMON almost ready for installation to include AIM implementation.

Billerica Hardware

*DSU190-B 3 units test out OK off line, one of these units went on line, replaced DSU190-A, on 8/12/75.

If this unit performs satisfactorily through the week-end an additional unit will go on line on Monday.

*MPC (190-B) This unit is ready to ship from Billerica.

Other

*Bill McFall is introduced as the responsible FED/DM for the MIT 6180 System.

A handwritten signature or set of initials, possibly 'BM', written in black ink. The signature is stylized and appears to be a cursive or shorthand representation of the name.