

RECEIVED  
NOV 3 1976  
J. H. SALTZER

FORUM LIST

W. J. Burner

D. Clark

C. Clingen

J. Gintell

C. Kessler

G. Lundberg

W. McFall

J. Regester

Prof. J. Saltzer

# Honeywell

TO: List of Attendees cc: List

SUBJECT: Forum Minutes for October 20, 1976

ATTENDEES: R. J. Chevalier E. D. Kleinow  
G. Dixon L. J. Ryan  
P. B. Kelley J. R. Steinberg

---

## HARDWARE - E. D. Kleinow

### DN355

- . System down because of LSLA problems. BD control board failed and is being replaced.
- . DN355 crashed system on Tuesday AM. FED replaced failing blower fan.

### Punch

- . Unit unavailable for 5 days. FED received and installed punch assembly on Tuesday.

### Processors

- . Major FCO (26 board swap) is half done. Kleinow estimates that the complete swap will be done by end of October.

### DSU190

- . Constant unreliability and failures of unit 8. FED has placed a MUR for this unit.

### MTH500

- . Unit is signaling what appears to be a premature EOF. FED will run tape T&D's.

SOFTWARE - G. Dixon

- . 29.3 installed
- . ITT overflow sending TTY wakeups from autocall line.  
Fix for this due in 30.1 or 30.2.

A handwritten signature or set of initials, possibly 'G. Dixon', written in dark ink. The signature is stylized and appears to be written over the list items.

RECEIVED  
DEC 15 1976  
J. H. SALTZER

FORUM LIST

W. J. Burner

D. Clark

C. Clingen

J. Gintell .

C. Kessler

G. Lundberg

J. Regester

Prof. J. Saltzer

J. R. Steinberg

# Honeywell

TO: List of Attendees

cc: List

SUBJECT: Forum Minutes for December 1, 1976

ATTENDEES: R. J. Chevalier                      W. McFall  
              P. B. Kelley                         L. J. Ryan  
              E. D. Kleinow                         R. A. Roach

---

## HARDWARE - E. D. Kleinow

### DSU190

- . Unit 3 had failing chip on DI board in MPC. FED replaced.  
Unit 1 - failure on fault detector board.  
Unit 4 - FED replaced 2 boards in the head select area.
- . FED has received new brake belts for disk units. Leo will arrange a schedule for installation.

### Processors

- . CPUA had CX board which failed on tester. This board was part of the "round robin" FCO. FED replaced 2 wire runs on the board and reinstalled.
- . CPUB has had several parity errors which appear to be cache related. FED is monitoring.
- . Both CP's are fully updated on the round robin FCO.

### SCU-B

- . Stor A. High voltage power supply failed and was replaced.

## SOFTWARE - P. B. Kelley

- . No significant software activity.
- . System 30.2 installed today.

### OTHER

- . Gean Kleinow announced that he will leave Honeywell on December 10 in order to devote full time to his business.