

RECEIVED  
JUN 3 1976  
J. H. SALTZER

F O R U M   L I S T

G. Ackerman-Lewis

D. Clark

C. Clingen

R. Daley

J. Gintell

P. B. Kelley

C. Kessler

G. Lundberg

J. Regester

Prof. J. Saltzer

J. R. Steinberg

# Honeywell

TO: List of Attendees

cc: List

SUBJECT: Forum Minutes for May 19, 1976

ATTENDEES: W. Burner                      W. McFall  
             R. J. Chevalier               R. A. Roach  
             W. J. Flaherty                   L. J. Ryan  
             E. D. Kleinow

---

## HARDWARE - E. D. Kleinow

- . MPC500 - RO board failing. FED located and replaced board.
- . SCU-B - St. B -FED located and replaced failing sense amp board.
- . SCU-B - ST. A -FED spared bit 16.
- . DSU190B - Unit #5 had damaged "pack-on" switch. FED replaced switch and spindle.
- . Processor A - Several processor failures reported. CMP, OP-not-complete, trouble faults. FED lowered margins to 4.5v in order to find failing chip.
- . Processor B - Crash because of BA board failure. FED working on problem.

## SOFTWARE - R. A. Roach

- . 28.5B - Installed and running.
- . 6 software crashes during this reporting period. Bugs causing these crashes were corrected in 28.4f and 28.5.

## BILLERICA - W. Flaherty

HSLA boards have been returned to Billerica.

