

~~F. H. Clark~~

then file

FORUM LIST

W. J. Burner

D. Clark ~~←~~

C. Clingen

J. Gintell

J. Krasula

G. Lundberg

H. Messmer

W. Ramirez

J. Register

Prof. J. Saltzer

L. Ryan

# Honeywell

TO: List of Attendees

cc: List

SUBJECT: FORUM MEETING FOR JULY 13, 1977

ATTENDEES: R. J. Chevalier  
P. B. Kelley  
R. A. Roach

M. Parkes  
S. D. Sprague  
J. R. Steinberg

---

## HARDWARE - S. D. Sprague

### MEMORY

- . SCU-A failing word mother board caused parity error crashing system twice. FED replaced board and has had no re-occurrence of the problem.

### DISK

- . DSU190, unit 14 errors caused 1 crash. FED replaced head pre-amp board.

### PROCESSOR

- . System loop on what looks like a STAC Q failure. FED couldn't find failure with T&D's.

### MSU0451's

- . Both units are on line.

## SOFTWARE - P. B. Kelley

- . Attempt to stop Initializer during reload caused crash.
- . NCP free table bug crashed system from ring 0.
- . iobm: trap installed for this bug.

*P.B.*