

~~Copy~~
file

11 August 1969

TO: Frank Donovan, New England Telephone
FROM: J. H. Saltzer, M.I.T. Project MAC
SUBJ: Known telephone problems related to 103E/level 8 installation.

Datasets believed to be down:

- A8 Hangs up during handshake; light bulb does not work.
- A14 Hangs up without turning on set ready.
- A22 Hangs up without turning on clear to send.
- B4 Hangs up immediately following handshake.

Datasets with small bugs but working well enough to use:

- A23 Flashes (as though ringing) when in use.

Troubles presumed to be in the Dataswitch:

- Trunk 132 (Dataset B6) Does not ring at 103E end of line.

Other problems:

Cabinet B pick-up function places ground on the picked-up line.

Datasets A7, A20, B4 and B5, among others, take longer than 12 seconds to disconnect if not hand shaken.

Copies: R. Daley
J. Grochow
F.J. Corbató