

Honeywell

D. Saltzer
For your info
FYI
~~Schwartz~~
check

RECEIVED
APR 25 1974
WJ Burner
CT Clingen
J. H. SALTZER
RC Bailey

To: List of Attendees
Subject: FORUM Minutes for 16 April 1974
Attendees: RJ Chevalier ED Kleinow
 DM Jordan RA Roach
 DA Kayden LJ Ryan

cc: JW Gintell
 RM Gross
 RE Hoffman
 JR Steinberg

HARDWARE - ED Kleinow

Bulk Store - second million words installed on Saturday from 6:00 a. m. to 9:00 a. m. Installation went very well.

Processor A - Op-not-complete - BH board had faulty chip. FED replaced it and it looks okay.

MTH500 - Kleinow feels that the hanging problem is a software bug. Noel Morris feels it is a problem with a special channel in the IOM. FED will investigate. Reliability on these units has improved significantly. Installation of next two (2) units will be determined at next FORUM.


PRT301 - Having paper mechanism problems. FED will investigate.

Hardware Bug #66 - MUN gets fixed overflow when moving O. FED has fix in-house but not installed.

SOFTWARE - DM Jordan

Software Bug List Status -

- #277 - Bug in printer __ status.....fix installed.
- #243 - Ring 0 NCP is version 1 pl/1....fix installed.
- #198 - Possible lost notify.....fix submitted; not installed.



RJC/kmp