

J H Saltzer fti: ~~Saltzer~~
club

Honeywell

for you RECEIVED
MAY 8 1974
J. H. SALTZER

To: List of Attendees
Subject: FORUM Minutes for 30 April 1974

cc: WJ Burner
CT Clingen
JW Gintell
RE Hoffman
JR Steinberg

Attendees: RJ Chevalier DM Jordan RA Roach
RC Daley ED Kleinow LJ Ryan
RM Gross DA Kayden

Hardware ED Kleinow

SCU Store B -- Two parity errors occurred last week. One crash resulted. FED ran T/D but found nothing. Kleinow says he needs more information.

PRT 301 -- Downtime caused by faulty VFU Lamp. FED replaced and it ran okay.

DSU190 -- Area 3 - over temperature sensor in power supply caused device inop status. FED moved sensors and it ran okay.

MPC500 -- Memory chip failed. Firmware would load but MPC would not work. FED replaced chip.

MTH500 -- Additional MTH505's have not been installed. FED (Kleinow) says the drives are running the way they should. T/D's do not show any problem areas. IPO (Daley) feels that the (expletive deleted) drives are not running with the write reliability that MIT needs. After lengthy discussions, Gross and Chevalier agreed to request an Engineering Representative from our Oklahoma City plant to visit MIT to review the installation and history of these drives.

Software DM Jordan

Software Bug List

- #264 - priority 2 I/O Daemon Loops Printing..... Fix for this bug installed last week.
- #277 - priority 1 I/O Coordinator sometimes loops....This continues to be a problem. no fix yet.

Roger Roach requested that CISL be asked to develop a BOS program to dump firmware. Dave Kayden will look into this.


RJC/emp