

Honeywell

Jerome H Saltzer for your info
F41
Schmitt
-Clark

To: List of Attendees
Subject: FORUM Minutes for 14 May 1974
Attendees: WJ Burner DM Jordan RA Roach
RJ Chevalier DA Kayden
RM Gross ED Kleinow

RECEIVED CT Clingen
RC Daley
MAY 20 1974 JW Gintell
RE Hoffman
J. H. SALTZER, J Ryan
JR Steinberg

HARDWARE ED Kleinow

- DSU190 - Area 6 Search Alerts reported last week were fixed on Thursday. FED replaced bad board.
- PRT301 - Paper Stacker problem; FED replaced "screw table" mechanism and resolved problem.
- MTH500 - Additional two drives put in place for installation. FCO must be installed prior to H1 firmware install.

Burner says no rental monies "NOT ONE DIME" will be paid on the 500's until they are running on service. An on-service date is dependent on MIT's confidence in these units.
- Other - The BSC355 Binary Synchronous Channel is of no use to MIT because software is needed to use it. It looks like useable software is one year away. FED will de-install and return this unit to Phoenix.

SOFTWARE DM Jordan

- Bug #277 - IO Coordinator sometimes loops...this bug has been fixed.
- New bug occurred last week in tape drive; fix submitted.
- Two emergency interrupts from 355 occurred during week. Software suspected; Synder is looking into this problem.

RJC/kmp