

Honeywell

JH Saltzer
For your info
RECEIVED
MAR 28 1974
J. H. SALTZER cc

Fil
Ch
Sch
CT Clingen
JW Gintell
RE Hoffman

To; List of Attendees
Subject: FORUM Minutes for 19 March 1974

Attendees: WJ Burner DM Jordan LJ Ryan
RJ Chevalier DA Kayden JR Steinberg
RC Daley ED Kleinow
RM Gross RA Roach

HARDWARE. ED Kleinow

- Processors -- two parity errors occurred last week. FED investigated but couldn't find any problem. FED will monitor.
- DSU191 -- Area 3 had six errors; area 10 had two errors last week. No crashes caused by these errors.
- Punch Peripheral Switch -- problem referenced last week regarding IMP difficulties seems to have disappeared with the installation of a new switch.
- MTH500 -- a number of mechanical problems have prevented Ryan from using the subsystem for saves. FED will concentrate efforts on this subsystem to define and correct these problems.

SOFTWARE. DM Jordan

--Priority 1 Bug List

- #272 - "Initializer Clobbers a pointer in system control's stack frame headed." A fix has been submitted for this problem but is not yet installed.
- #243 - "Ring 0 NCR is Version 1 pl 1" fix has been submitted but not installed.
- #198 - "Possible lost notify" S. Webber indicates that he knows what this problem is being caused by but has not yet submitted a fix.

OTHER

Burner and Ryan requested that installation plans for additional MTH500's be moved out by two weeks because of delays.

RJC/kmp