

MOMENT RESISTING BEAM SCHEDULE																				
MARK	SECTION	SUPPORT SOUTH/WEST F.O. SUPPORT	SPAN	F.O. SUPPORT	SUPPORT NORTH/EAST	REMARKS	MARK	SECTION	SUPPORT SOUTH/WEST F.O. SUPPORT	SPAN	F.O. SUPPORT	SUPPORT NORTH/EAST	REMARKS	MARK	TYPE	SUPPORT SOUTH/WEST F.O. SUPPORT	SPAN	F.O. SUPPORT	SUPPORT NORTH/EAST	REMARKS
SB4-135	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-119	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-103	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-136	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-120	III	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-104	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-137	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-121	III	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-105	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-138	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-122	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-106	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-139	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-123	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-107	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-140	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-124	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-108	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-141	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-125	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-109	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-142	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-126	III	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-110	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-143	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-127	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-111	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-144	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-128	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-112	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-145	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-129	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-113	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-146	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-130	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-114	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-147	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-131	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-115	II	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-148	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-132	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-116	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'				
SB4-149	I	#5 #5 #3 2' 9 0/2 1/2" BAL @ 5" MAX 9 0/2 1/2" 2'					SB4-133	I	#5 #5 #3 2' 9 0/2 1/2"											

[illegible]