

JAS

Frank,

5 Dec

following problems on dataset racks:

A17	Indicator lt out
A18	Won't detect hangup.
A22	"
A28	Light
B6	Doesn't answer (previously updated)
GE x275 (103A)	Auto-ans light out.

In addition, electrician dropped the power circuit for the two boxes today, they seem to be ok, but you might want to take a look.

(Garmon

Copies: Saltzer  
Grochow