

Beilon problem:

1. How do we place an open order, to get data sets installed, wires laid + checked, to get quick expansion capability, ~~in the~~ when we find the correct direction of expansion?
2. Can't we use 103E being feature on 4 digit loops, only on one trunk (?.)
3. What is holding up installation of M37's?
4. Slow service on 103E's
15 problems, none fixed
20 not yet installed, 4c in.