

Saltzer

October 6, 1969

TO: Administrative Distribution
FROM: E. T. Reardon
SUBJECT: GE-645

Date		Status
	1) Memories Remarks	
9/29/69	Mem H - multiple bit drop. Adjusted strobe timing replaced in PWB in stack 6	SAT
9/30/69	Mem G - recoverable parity LOC334150 - complete schmoo on 10/1	LIMP
10/2/69	Mem - parities, possible bit no. 1 pick up, picking bit 2 on bucket "001", changed bucket with spare	SAT
10/2/69	Mem H - bit 44LS odd, moved and timing - switch parity PWB	SAT
	2) Tapes Remarks	
10/3/69	Peripheral Switch & Readers not working with errors-banned. Corrected faulty switch contact in S12	SAT
	3) DSIO's Remarks	
10/2/69	DSIOA - airfault - swapped bronze filter	SAT