To:

Distribution

From:

David M. Jordan

Date:

December 6, 1974

Subject: Installation of Salvager 2.28

The Salvager system 2.28 was updated at 3:00 PM on Tuesday, November 26, 1974. This system included a change to cause more information to be printed when errors are encountered, a minor change to the processing of reused addresses to cause them to be awarded to the root or the fsdct (if those segments are involved), and a change to the printer handling package to run all of the currently available printers. In addition, all hardcore changes through MSS 24.2 and the change to the directory hash table usage were incorporated with this system.

### I. System Change Log

#### Chng MCR Change

- 0005 392 Modified the salvager to cause the printing of names and threads found to be in error.
  - 529 Modified the salvager to cause pages in dispute due to reused addresses to be awarded to the root or the fsdct.
  - 571 Modified the salvager to process the padding fields in a directory entry so they can be used in the implementation of AIM.
- 0006 031 Modified the salvager print package to continue working with changes made to support broad capabilities in Multics.
  - 738 Modified the salvager print package to operate properly 749 with the PRT-303, PRU-1200, and PRU-1600 printers.

Multics Project Internal working documentation. reproduced or distributed outside the Multics Project.

## II. Segment Change Log

Segment Name	Bound Segment	<u>Change #</u>
<pre>periph_io.pl1 rswalm salv_activator.pl1 salv_initializer.pl1 salvager.pl1 utility_print.pl1</pre>	bound_util_print bound_offline_salvager bound_offline_salvager bound_offline_salvager bound_util_print	R 0006 D 0005 R 0005 R 0005 R 0005 R 0006
Bind Files		
bound_offline_salvager.	R 0005	

# III. Bound Segment Change Log

Bound Segment	Bound	,	Se	gm	en	t
---------------	-------	---	----	----	----	---

## Change

bound_offline_salvager	Replaced	salv_activator salvager
	Deleted	rsw_
bound_util_print	Replaced	periph_io utility_print

## IV. Header Change Log

The salvager edit header was modified to remove an obsolete reference to "tape\_data" and to cause "lock\_seg" to be added to the header before salv\_check\_thread\_seg.