

November 4, 1969

MEMORANDUM

To: Frank Donovan, New England Telephone
From: Jerry Saltzer, M.I.T., Project MAC
Subject: 103E Dataset Troubles

Problems:

- A14 Does not answer calls despite terminal ready
- A35 Does not turn on "clear to send"
- A23 Light blinks as though ringing when in use.

The following datasets are susceptible to overload by the calling party, and thus do not work for some callers:

A36, B30, B31, B35, B38.

JHS/bm

xc: F. J. Corbato
R. Daley
J. Grochow
Operations


November 20, 1969

MEMORANDUM

To: Frank Donovan, New England Telephone
From: Jerry Saltzer, M.I.T., Project MAC
Subject: 103E Dataset Troubles

Problems

- A7 Panel indicator lamp burned out
- A9 Panel indicator lamp burned out
- A14 Does not always answer calls despite terminal ready. When it does answer, it immediately hangs up.
- A26 Answers, but does not inform computer that it did. (CE lead is not turned on.)



JHS/bm

cc: F. J. Corbato
R. Daley
J. Grochow
C. Garman
Operations