

Honeywell

J. Saltzer


For your info

fyi
~~Schmidt~~
Clock

To: List of Attendees
Subject: FORUM Minutes for 2 April 1974

cc: CT Clingen
RC Daley
JW Gintell

Attendees: WJ Burner DM Jordan LJ Ryan
RJ Chevalier ED Kleinow JR Steinberg
RM Gross RA Roach



Hardware - ED Kleinow

BSC - unit down for a 22 hour period over weekend. Problem found to be a shorted wire on the back panel. FED located and corrected.

MPC181 - Memory chip failed. Located and corrected.

PRT301 - Down because of apparent controller problems.

MTH500 - AREA 3 having various problems - it randomly drops in check status and stretched a tape last week because of a bad servo board.

Software - DM Jordan

Last week went very well loosing less than 5% of the scheduled time and having only two (2) crashes.

Other

Bulk Store is scheduled to arrive this week. Installation of this unit is tentatively scheduled for next week.

RJC/kmp