

Honeywell

J H Saltzer
for your info

RECEIVED
MAR 2 1974
CU: n. SALTZER

F41
Schmidt

To: List of Attendees
Subject: FORUM Minutes for 12 March 1974

Attendees: WJ Burner RM Gross ED Kleinow
 RJ Chevalier DM Jordan RA Roach
 RC Daley DA Kayden LJ Ryan

JW Gintell
RE Hoffman
JR Steinberg

HARDWARE ED Kleinow

- Processors - op-not-complete, CPU B. Problem occurred once last week.
 - SCU-C - errors occurred - problem with word mother board
 - CSM-7 - errors occurred - problem with DLP board - board replaced and ran okay.
- DSU191 - Area 0 caused crash - FED found timing problem and corrected.
 - Area 11 arm clamp had to be replaced - running okay now.
- Other hardware - punch peripheral switch seems to be causing strange problems - i.e., when the switch is used it appears to have an adverse affect on the IMP.

SOFTWARE DM Jordan

- Priority 1 bugs (Reference bug list)
 - 272 - This is a new bug - occurred last week.
 - 243 - Wells says he has fix but it is not submitted for installation yet.
 - 198 - Webber assigned and feels he has located the possible cause of error conditions - fix not submitted yet.

HARDWARE To Be Installed

- MTH500 - two units are scheduled to ship on 18 March 1974 - expect arrival by 22 March 1974. Additional two units scheduled to ship 1 April 1974.
- Bulk Store - second million words scheduled to ship by 31 March 1974.

RJC/